

Landesgesellschaft
Österreich

Certificate of constancy of performance

Certificate - No.: 0531 – CPR – 1317 – 0401

In compliance with Regulation 305/2011/EU of the European Parliament and of the Council of 9 March 2011 (the Construction Products Regulation or CPR), this certificate applies to the construction product

Super-Rail doppelt H4b

Containment level:	N2	H4b	L4b
Normalized working width:	W4	W5	W5
Impact severity:	B	B	B
Normalized dynamic deflection:	0.3m	0.9m	0.9m
Normalized vehicle intrusion:	NPD	VI8	VI8
Resistance to snow removal:		Class 3	

durability: galvanized in accordance with EN ISO 1461 or EN 10346

produced for
ALKA Sanayi Insaat ve Ticaret AS
Cumhuriyet Mah. Erhan Sok. 10
41435 Cayirova
Turkey

and produced in the manufacturing plant
ALKA Sanayi Insaat ve Ticaret AS
Cumhuriyet Mah. Erhan Sok. 10
41435 Cayirova
Turkey

This certificate attests that all provisions concerning the assessment and verification of constancy of performance described in Annex ZA 1.b of the standard

EN 1317-5:2007+A2:2012/AC:2012

under system 1 for the performances set out above are applied and that the construction product fulfils all the prescribed requirements for these performances.

This certificate was first issued on 04.05.2012, based on the assessment report 27056_AL_rev1/06.08.2019 and will remain valid as long as the test methods and/or factory production control requirements included in the harmonised standard, used to assess the performances of the declared essential characteristics, do not change, and the construction product, and the manufacturing conditions in the plant are not modified significantly, unless suspended or withdrawn by the product certification body.

Wien, 02.09.2019



TÜV SÜD Landesgesellschaft Österreich GmbH Zertifizierungsstelle für Produkte Arsenal, Objekt 207 1030 Wien

Landesgesellschaft
Österreich

**Annex to
certificate of constancy of performance
Certificate - No.: 0531 – CPR – 1317 – 0401**

For the construction product Super-Rail doppelt H4b

**Placed on the market by ALKA Sanayi Insaat ve Ticaret AS
Cumhuriyet Mah. Erhan Sok. 10
41435 Cayirova**

Modification 1:Approved on
12.04.2011Corrosion protection of beams:

Corrosion protection of the A-beam (L1.1-101) and B-beam (L1.1-102) can be done via hot dip galvanizing according to DIN EN ISO 1461:2009 or alternatively via continuous galvanizing according to DIN EN 10346:2009 with steel bands with zinc(Z) (DIN EN 10346-S250GD+Z600-N-A-C) or respectively with zinc-aluminum(ZA) (DIN EN 10346-S250GD+ZA300 and ZA600-N-A-C)-coating. The mentioned modification was judged and assessed in the test report 15915.

Modification 2:Approved on
12.04.2011Supporting Bracket:

Supporting Brackets were made of S355JR (RAL part no. 004.00 and 004.10) for the ITT. The use of S235JR can be seen as equivalent. The mentioned modification was judged and assessed in the test report 15953.

Modification 3:Approved on
16.04.2012Meter holes:

The rails profile A and profile B may be modified with additional elongated holes according to RAL-Drawing no. L1.1-101 and L1.1-102. The mentioned modification was judged and assessed in the test report 19250.

Modification 4:Approved on
27.12.2012Equivalence of A and B profile:

The A-beam (L1.1-101) and B-beam (L1.1-102) with the additionally needed parts can be seen as equivalent. The mentioned modification was judged and assessed in the test report 16975_Rev01.

Modification 5:Approved on
16.02.2015Change of nut and bolt between beam and deformation element:

The round head bolt with nose M 16x45, 4.6 with nut 5 (40.01) should be replaced by the round head bolt with hexagon M 16x45, 8.8 with nut 8 (40.04). The mentioned modification was judged and assessed in the report 28268_1.

Modification 6:Approved on
23.12.2016Omission of bolts with adapted butt joint:

When using the adapted longer butt joint, the two M 14 bolts can be omitted in the box profile butt joint. The mentioned modification was judged and assessed in the report 28268_3_Rev02.

Wien, 02.09.2019

Notified body, No. 0531

(Dipl.-Ing. Gerald Bachler)

Landesgesellschaft
Österreich**Zertifikat der Leistungsbeständigkeit****Zertifikat- Nr.: 0531 – CPR – 1317 – 0401**

Gemäß der Verordnung (EU) Nr. 305/2011 des Europäischen Parlaments und des Rates vom 9. März 2011 (Bauproduktenverordnung - CPR), gilt dieses Zertifikat für das Bauprodukt

Super-Rail doppelt H4b

Aufhaltstufe:	N2	H4b	L4b
Normalisierter Wirkungsbereich:	W4	W5	W5
Anprallheftigkeitsstufe:	B	B	B
Normalisierte dyn. Durchbiegung:	0,3m	0,9m	0,9m
Normalisierte Fahrzeugeindringung:	NPD	VI8	VI8
Beständigkeit Schneeräumung:		Klasse 3	

Dauerhaftigkeit: verzinkt nach EN ISO 1461 oder alternativ nach EN 10346

Hergestellt von

ALKA Sanayi Insaat ve Ticaret AS
Cumhuriyet Mah. Erhan Sok. 10
41435 Cayirova
Türkei

und in folgendem Werk gefertigt

ALKA Sanayi Insaat ve Ticaret AS
Cumhuriyet Mah. Erhan Sok. 10
41435 Cayirova
Türkei

Dieses Zertifikat bescheinigt, dass alle Vorschriften über die Bewertung und Überprüfung der Leistungsbeständigkeit im Anhang ZA.1.b der harmonisierten Norm

EN 1317-5:2007+A2:2012/AC:2012

entsprechend System 1 angewendet werden und dass das Bauprodukt alle darin vorgeschriebenen Anforderungen erfüllt.

Dieses Zertifikat wurde erstmals am 04.05.2012 ausgestellt auf Basis des Bewertungsberichts 27056_AL_rev1/06.08.2019 und bleibt gültig, solange sich die in der harmonisierten Norm genannten Prüfverfahren oder Anforderungen der werkseigenen Produktionskontrolle zur Bewertung der Leistung der erklärten Merkmale nicht ändern und das Produkt und die Herstellungsbedingungen im Werk nicht wesentlich geändert werden.

Wien, 02.09.2019



(Dipl.-Ing. Gerald Bachler)

TÜV SÜD Landesgesellschaft Österreich GmbH Zertifizierungsstelle für Produkte Arsenal, Objekt 207 1030 Wien

Landesgesellschaft
Österreich

**Anhang zum
Zertifikat der Leistungsbeständigkeit
Zertifikat- Nr.: 0531 – CPR – 1317 – 0401**

Für das Bauprodukt **Super-Rail doppelt H4b**
In Verkehr gebracht **ALKA Sanayi Insaat ve Ticaret AS**
durch **Cumhuriyet Mah. Erhan Sok. 10**
 41435 Cayirova

Modifikation 1:Genehmigt am
12.04.2011Korrosionsschutz von Schutzplankenholmen:

Der Korrosionsschutz von Schutzplankenholmen Profil A (L1.1-101) und Profil B (L1.1-102) erfolgt als Stückverzinkung nach EN ISO 1461 (Ausgabe 10/2009) oder alternativ durch die Verwendung von kontinuierlich schmelztauchveredeltem Stahlband („Bandverzinken“) mit Zink (Z)- nach EN 10346-S250GD+Z600 bzw. mit Zink-Aluminium (ZA)-Überzug nach EN 10346-S250GD+ZA300 (Ausgabe 10/2015).

Gegenständliche Modifikation wurde im Prüfbericht 15915 beurteilt und bewertet.

Modifikation 2:Genehmigt am
12.04.2011Stützbügel:

Für die Stützbügel (RAL Teile-Nr. 004.00 und 004.10) wurde beim ITT die Stahlsorte S355JR verwendet. Wird die Stahlsorte S235JR verwendet, kann dies als gleichwertig angesehen werden. Gegenständliche Modifikation wurde im Prüfbericht 15953 beurteilt und bewertet.

Modifikation 3:Genehmigt am
16.04.2012Meterlochung:

Für die Schutzplankenholme Profil A (L1.1-101) und Profil B (L1.1-102) ist eine Verwendung von Holmen mit Zusatzlochung bei 1,0 m und 3,0 m („Meterlochung“) gleichwertig möglich. Gegenständliche Modifikation wurde im Prüfbericht 19250 beurteilt und bewertet. Für das System kann der Analogieschluss gezogen werden.

Modifikation 4:Genehmigt am
27.12.2012Schutzplankenholme A- und B-Profil:

Verwendung von Schutzplankenholmen Profil A (L1.1-101) und Schutzplankenholmen Profil B (L1.1-102) in Verbindung mit den jeweils zugehörigen Bauteilen ist gleichwertig möglich. Gegenständliche Modifikation wurde im Prüfbericht 16975_Rev1 beurteilt und bewertet.

Modifikation 5:Genehmigt am
16.02.2015Änderung Verschraubung zwischen Holm und Deformationselement:

Die HRK-Schraube mit Nase M 16x45, 4.6 mit Mutter 5 (40.01) soll durch die HRK-Schraube mit Sechskant M 16x45, 8.8 mit Mutter 8 (40.04) ersetzt werden. Gegenständliche Modifikation wurde im Bericht 28268_1 beurteilt und bewertet.

Modifikation 6:Genehmigt am
23.12.2016Wegfall Schrauben bei geändertem Stoßverbinder:

Bei Verwendung des geänderten längeren Stoßverbinders können bei der Kastenprofil-Stoßverbindung die beiden M 14 Schrauben weggelassen werden. Gegenständliche Modifikation wurde im Bericht 28268_3_Rev02 beurteilt und bewertet.

Wien, 02.09.2019

Notified body, No. 0531



(Dipl. – Ing. Gerald Bachler)

TÜV SÜD Landesgesellschaft Österreich GmbH Zertifizierungsstelle für Produkte Arsenal, Objekt 207 1030 Wien